

TCDU Dispenser Replacement Error

Usually the dispenser is going to be set to a test mode. If you don't change the dipswitches at the bottom of the dispenser then you will run into a CDNXX error.

Check underneath the dispenser and inspect the dip switches (outlined in yellow). Make sure the switch is "ON" for number 1 and "OFF" for 2, 3 and 4 and turn the ATM back on. The ATM should cycle the dispenser on boot up and get rid of the error.

